

PARTNER



AHERA Three-Year Reinspection Report Round 2: Fall 2018

**Kenilworth Public Schools
Harding Elementary School
426 Boulevard
Kenilworth, New Jersey 07033**

Partner Project No. 18274462

Date: December 20, 2018



December 20, 2018

Job No. 18274462

Kenilworth Public Schools
401 Monroe Avenue
Kenilworth, New Jersey 07033

ATTN: Mr. Chris Caponegro
Supervisor of Building and Grounds

**Re: AHERA Three-Year Reinspection Report – Fall 2018
Harding Elementary School
Kenilworth, New Jersey**

Dear Mr. Caponegro:

Acting in our capacity as an asbestos management consultant retained by Kenilworth Board of Education, Partner Engineering and Science, Inc. (Partner) has recently completed the three-year reinspection required for the subject facility by the "Asbestos-Containing Materials in Schools Rule" (40 CFR 763, Subpart E). The surveillance was performed pursuant to 40 CFR 763.92(b) by an accredited AHERA Building Inspector.

Repair and/or removal of the damaged ACBM and implementation of continued operations and maintenance activities are indicated as appropriate response actions. Please see Table 1 for specific locations.

Thank you for the opportunity to have been of service to you on this project. Should you have any questions, please contact our office.

Respectfully,
PARTNER ENGINEERING AND SCIENCE, INC.



Michelle Gomez
Senior Industrial Hygienist

Reinspection By: Michelle Gomez
AHERA Inspector #: NAETI-52051

Date of Reinspection: October 26, 2018

TABLE 1
ASBESTOS-CONTAINING BUILDING MATERIAL (ACBM)
IDENTIFIED BY LOCATION

HARDING ELEMENTARY SCHOOL
(426 BOULEVARD)

Notes: sf = square feet (of surfacing material)
lf = linear feet
ND = no damage to ACM
“*” = concealed beneath carpeting or 12”x12” floor tile
“**” = enclosed; access limited

HOMOGENEOUS ID NO. TYPE OF ACM	LOCATION	APPROXIMATE AMOUNT	RESPONSE ACTION
06/White matrix block heating pipe insulation	Crawlspace (1951 Wing)	3,682 lf	Scattered damaged throughout
	2 nd Floor Custodian Closet 207	10 lf	ND/O&M
07A/Grey cementitious pipe fitting insulation associated with fibrous glass pipe insulation (1964 Wing)	Room 164, Bathrooms (estimated, in wall and ceiling plenum)	8 lf	ND/O&M
	Room 160, Bathrooms, (estimated)	8 lf	ND/O&M
	Boys’ Room	4 lf	ND/O&M
	Girls’ Room	4 lf	ND/O&M
	Room 159, Janitor’s Closet	4 lf	ND/O&M
	Room 163, Janitor’s Closet	1 lf	ND/O&M
	Room 165, Janitor’s Closet	7 lf	ND/O&M
07B/ Grey cementitious pipe fitting insulation associated with fibrous glass pipe insulation (1971 Wing)	Room 167	4 lf	1 lf damaged**
	Room 169	3 lf	1 lf damaged**
	Room 166	1 lf	ND/O&M
07C/Grey layered wafer pipe insulation and associated cementitious pipe fitting insulation (1956 Wing)	Classroom 108	20 lf	ND/O&M
	Classroom 109 (concealed in chase)	Not quantified	ND/O&M
	Classroom 111	30 lf	2 lf damaged**

HOMOGENEOUS ID NO. TYPE OF ACM	LOCATION	APPROXIMATE AMOUNT	RESPONSE ACTION
07F/White matrix block pipe insulation and associated cementitious pipe fitting insulation (1956 Wing)	Janitors Closet 115	20 lf	ND/O&M
08/Grey cementitious pipe fitting insulation on roof drains	2 nd Floor Hallway, above plaster ceiling	22 lf (estimated)	ND/O&M
11A/Brown 9"x9" floor tile (1923 Wing)	1 st and 2 nd Floor Hallway	3,200 sf	ND/O&M
	Stairwells	900 sf	ND/O&M
	Room 113, Storage Closet	84 sf	ND/O&M
	Room 112, Storage Closet	60 sf	ND/O&M
	Storage Closets Second Floor 242	120 sf	ND/O&M
11B/Dark brown 9"x9" floor tile	1 st Floor, Hallway	1,050 sf	ND/O&M
	Room 106A, Closet	96 sf	ND/O&M
	Room 117, Storage	180 sf	ND/O&M
	Room 160 (half 12"x12")	700 sf	ND/O&M
	Room 164 (half 12"x12")	700 sf	ND/O&M
	Room 163*	72 sf	ND/O&M
11C/Tan with yellow and brown 9"x9" floor tile	Room 206*	800 sf	ND/O&M
	Room 240*	800 sf	ND/O&M
	Room 210	800 sf	ABATED
	Room 212	800 sf	ND/O&M
	Room 234	800 sf	ND/O&M
	Room 204	800 sf	ND/O&M
	Room 201*	1,560 sf	ND/O&M
	Room 114, Meter Room	220 sf	ND/O&M
	2 nd Floor Upper Hallway	220 sf	ND/O&M
	11D/Grey 9"x9" floor tile	Room 203*	800 sf
Room 237		600 sf	ND/O&M
Room 239		800 sf	ND/O&M

HOMOGENEOUS ID NO. TYPE OF ACM	LOCATION	APPROXIMATE AMOUNT	RESPONSE ACTION
11D/Grey 9"x9" floor tile (continued)	Room 241	800 sf	ND/O&M
	Room 205, Special Services*	1,400 sf	ND/O&M
	Room 109	620 sf	ND/O&M
11E/Dark green streaked 9"x9" floor tile	Room 145	800 sf	ND/O&M
	Room 147	800 sf	ND/O&M
	Basement, Bomb Shelter	150 sf	150 sf Damage Repair/Replace
	Room 149	750 sf	ND/O&M
11EE/Light Green with green and white streaks 9"x9" floor tile	Room 108	1,100 sf	ND/O&M
11FF/White with pink and brown 12"x12" floor tile	Supply Closet	80 sf	ND/O&M
	Room 170 (200 sf Under Carpet)	850 sf	ND/O&M
	Room 168	850 sf	ND/O&M
	Room 258	720 sf	ND/O&M
	Room 166	40 sf	ND/O&M
	Room 160	250 sf	ND/O&M
	Room 167 (Half Under Carpet)	453 sf	ND/O&M
11I/Tan with brown 12"x12" floor tile 11I/Tan with brown 12"x12" floor tile (continue)	Room 169 (200 sf Under Carpet)	756 sf	ND/O&M
	Art Room 202	900 sf	ND/O&M
11J/White/olive 12"x12" floor tile (1964 Wing)	2 nd Floor Hallway adjacent Room 255	900 sf	ND/O&M
11K/Peach 9"x9" floor tile (1956 Wing)	2 nd Floor Hallway	220 sf	ND/O&M
11L/Tan/rust 9"x9" floor tile (1956 Wing)	Admin Break Room/Room 106A	60 sf	ND/O&M
	Custodial Office 152	300sf	ND/O&M
	Room 235, Storage	275 sf	ND/O&M
	Room 205B, Storage	196 sf	ND/O&M
	Room 207, Janitor's Closet	131 sf	ND/O&M
	Room 243, Guidance	120 sf	ND/O&M

HOMOGENEOUS ID NO. TYPE OF ACM	LOCATION	APPROXIMATE AMOUNT	RESPONSE ACTION
11L/Tan/rust 9"x9" floor tile (1956 Wing) (continued)	Room 165, Storage Closet	35 sf	ND/O&M
	Room 205B Storage	196 sf	ND/O&M
	Room 242	336 sf	ND/O&M
	Room 251 Storage	320 sf	ND/O&M
11M/Tan with yellow, blue and brown streaks 9"x9" floor tile (1964 Wing)	Room 151*	200 sf	ND/O&M
	Room 153	200 sf	ND/O&M
	Room 156	750sf	ND/O&M
	Room 155	350 sf	ND/O&M
	Room 154*	750 sf	ND/O&M
	Room 245	680 sf	ND/O&M
	Room 246, 248*	1,250 sf	ND/O&M
	Room 250	1,020 sf	ND/O&M
	Room 208	800 sf	ND/O&M
	11N/Tan with black 9"x9" floor tile	Room 150	800 sf
Room 148		800 sf	ND/O&M
Room 164 (Half Under Carpet)		850 sf	ND/O&M
Room 160 (Half Under Carpet)		850 sf	ND/O&M
Room 233, Guidance		470 sf	ND/O&M
Room 250, Hallway		80 sf	ND/O&M
11O/Light brown 12"x12" floor tile	Cafeteria/Kitchen	5,000 sf	ND/O&M
11P/Dark brown 12"x12" floor tile	Refrigerator Kitchen Storage/Room 106	128sf	ND/O&M
11Q/Dark brown 12"x12" floor tile	Lunchroom/Kitchen	75 sf	ND/O&M
30/Mastic associated with 9"x9" and 12"x12" floor tiles	Throughout the building	Not quantified	ND/O&M
	Basement, Bomb Shelter	720 sf	ND/O&M
1AA/Teal with white streaks 9"x9" floor tile	Room 143 (edging)	45 sf	ND/O&M

HOMOGENEOUS ID NO. TYPE OF ACM	LOCATION	APPROXIMATE AMOUNT	RESPONSE ACTION
2AA/White with gray streaks 9"x9" floor tile	Room 143	90 sf	ND/O&M
3AA/Mauve speckled 12"x12" floor tile	Room 255	700 sf	ND/O&M

R:\Solutions\Jobs\Kenilworth BOE\18274462-HS\Report\Insp Rpt\Fall 2018\18274462-R-Harding Elementary School_2018 Fall Surveillance Report.docx